

# Dust and Sweep Metals Area

## \*Safety\*

- Wear a dust mask (if you do not have your own, disposable masks are available in the custodial room).

## \*Task List\*

For each metal shop tool:

1. Use a shop vac or dust brush to remove dust from all visible surfaces.
2. Sweep the floors of the general metals, CNC plasma, welding, sand blasting, and precision metals areas.
3. Gathered debris should be tossed into the rolling trash cans.

---

Revision #1

Created 2 June 2025 15:03:52 by Bookstack Admin

Updated 14 June 2025 15:10:55 by Bookstack Admin