

Dust sheet metals area

Safety

- Wear a dust mask.
- Wear safety glasses.
- Unplug all electrical equipment before cleaning.

Task List

With a dry cloth, wipe down all external surfaces of the sheet metal tools:

- shear
- slip roller
- finger brake
- shrinker/stretcher
- turret punch
- notcher

Revision #3

Created 2 June 2025 14:47:58 by Bookstack Admin

Updated 25 April 2026 16:50:23 by Bookstack Admin