

# Fusion 360

- [Design Tips for Manufacturing](#)

# Design Tips for Manufacturing

- Avoid importing SVGs or STLs until late in design, as they are computationally complex to operate on.
- Try using F360 parameters for dimensions you expect may change as you begin prototyping - these allow you to easily re-dimension the model without editing specific features.