

Design Tips for Manufacturing

- Avoid importing SVGs or STLs until late in design, as they are computationally complex to operate on.
- Try using F360 parameters for dimensions you expect may change as you begin prototyping - these allow you to easily re-dimension the model without editing specific features.

Revision #3

Created 31 December 2024 20:10:14 by Scott Martin

Updated 13 January 2025 15:01:54 by Scott Martin