Member Notes

Mods

This printer has a series of community mods that improve it’s performance and safety
https://github.com/UnifiedEngineering/T-962-improvements
https://www.youtube.com/watch?v=bgVey2O3W2k

We should check the oven to see if the tape has been replaced and the ground has been fixed.

we should consider if we install the open source firmware and install the temperature sensor for better performance.

Revision #2
Created 2025-01-10 16:17:12 UTC by Paul Mazaitis
Updated 2026-06-01 19:34:14 UTC by Manager Scott Martin