

DECKEL

GK 12
GK 21

ERSATZTEIL-PLAN

Universal Gravier- und Kopierfräsmaschinen

SPARE PARTS CATALOGUE

Universal Engraving and Profiling Millers

PLAN DE PIÈCES DE RECHANGE

Fraiseuses à graver et à copier universelles

SCHEMA DELLE PARTI DI RICAMBIO

Macchine universali per incidere e copiare

CATÁLOGO DE PIEZAS DE RECAMBIO

Fresadora-grabadora y copiadora


RESERVDELSLISTA


Universala gravyr- och kopierfräsmaskiner


ПЛАН ЗАПАСНЫХ ЧАСТЕЙ


**Универсальные гравировальные и
копировально-фрезерные станки**





























4550 - 2200 = 220 V/50 Hz
4550 - 1100 = 110 V/50 Hz























4600 40 338 80




4600 40 335 80




4600 40 328 80



4500 40 338 80



4500 40 335 80



6001 40 311 80

