

Soldering Iron

- Check Consumables

Check Consumables

- Check if the tip is in good condition: no obvious damage, good point, no deep pitting. Replace tip if needed.
- Check the sponge to make sure it is in good condition. Replace sponge if needed.