

Clean welding helmets and jackets

Gloves

Inspect gloves. Put in a purchase request for any pairs that have holes or excessive wear (don't throw them out until we have replacements)

- Purchase request: <https://protohaven.org/purchasing>

Helmets

1. Make a purchase request if the helmet is nonfunctional:
 - a. If there are holes or excessive wear
 - b. If the head strap is broken
 - c. If the lens is difficult to see through
2. Confirm the helmets auto-darken - shine a phone light on them or take them into direct sunlight
3. Wipe surfaces with a damp cloth

Jackets

1. Inspect and report any holes, wear, or more than 3 missing buttons
2. If any are excessively dirty, file a tool report so they can be machine washed (warm water, regular detergent, high water level)

Revision #1

Created 2 June 2025 14:52:18 by Bookstack Admin

Updated 14 June 2025 15:10:55 by Bookstack Admin