

Dust and Sweep Forge Area

Safety

- Wear a dust mask.
- Wear safety glasses.

Task List

DO NOT dust the interior of the forges as improper cleaning may damage the refractory material.

1. Use a shop vac or dust brush to remove dust from all visible surfaces, paying special attention to the tables, tool caddies, and other "installed" furniture in the space.
2. Sweep the floor.
3. Dispose of any debris in a nearby trash can.

Revision #1

Created 2 June 2025 14:59:15 by Bookstack Admin

Updated 14 June 2025 15:10:55 by Bookstack Admin