

# Dust sheet metals area

## \*Safety\*

- Wear a dust mask.
- Wear safety glasses.
- Unplug all electrical equipment before cleaning.

## \*Task List\*

With a damp cloth, wipe down all external surfaces of the sheet metal tools:

- shear
- slip roller
- finger brake
- shrinker/stretcher
- turret punch
- notcher

---

Revision #1

Created 2 June 2025 14:47:58 by Bookstack Admin

Updated 14 June 2025 15:10:55 by Bookstack Admin