

Powder Coating - Clean out hooks & wires

Task List

- Throw out any wire pieces that are excessively twisted/kinked and not useful for holding up parts.
- Sandblast any larger/stiff hooks that are fully coated in powder so they can better ground the parts that'll be hanging from them.
- Brush/vacuum around and inside the hooks/wires caddy to get rid of any loose powder.

Revision #1

Created 2 June 2025 15:16:16 by Bookstack Admin

Updated 2 June 2025 15:16:56 by Bookstack Admin