



VCarve Allowance Offset

Toolpath	Machine Vectors	Offset Allowance	Ref#	Impact on Cut
Profile	Outside/Right	Positive	1	Moves cut line away from vector (outward) resulting in a larger inner shape
		Negative	2	Moves cut line toward vector (inward) resulting in a smaller inner shape
	Inside/Left	Positive	3	Moves cut line away from vector (inward) resulting in a smaller inner shape
		Negative	4	Moves cut line toward vector (outward) resulting in a larger inner shape
Pocket	N/A	Positive	5	Moves cut line away from vector (inward) resulting in a smaller pocket
		Negative	6	Moves cut line toward vector (outward) resulting in a larger pocket


Toolpath - Profile
Machine Vector - Outside/Right
Allowance Offset - Positive




Toolpath - Profile
Machine Vector - Outside/Right
Allowance Offset - Negative




Toolpath - Profile
Machine Vector - Inside/Left
Allowance Offset - Positive



Toolpath - Profile
Machine Vector - Inside/Left
Allowance Offset - Negative



Toolpath - Pocket
Allowance Offset - Positive



Toolpath - Pocket
Allowance Offset - Negative

