

Member Notes

Mods

This printer has a series of community mods that improve it's performance and safety

<https://github.com/UnifiedEngineering/T-962-improvements>

<https://www.youtube.com/watch?v=bgVey2O3W2k>

We should check the oven to see if the tape has been replaced and the ground has been fixed.

we should consider if we install the open source firmware and install the temperature sensor for better performance.

Revision #2

Created 10 January 2025 16:17:12 by Paul Mazaitis

Updated 1 June 2026 19:34:14 by Manager Scott Martin